



09/11/2014

New Safety Recall Advanced Communication – P57091114

Chrysler Group LLC (Chrysler) announced a safety recall on some 2008 model year (XK) Jeep Commander, (WK) Jeep Grand Cherokee and (LX) Chrysler 300 vehicles.

Some of the above vehicles may experience a Frequency Operated Button Ignition Key (FOBIK) that may stick between the “START” and “RUN” position. This may result in the loss of certain electrical features.

A FOBIK that is stuck between the “START” and “RUN” position while driving could experience an unintended change in ignition switch position to the “OFF” or “ACCESSORY” position due to “FOBIK spring back.” FOBIK spring back to the “OFF” or “ACCESSORY” ignition position may result in the loss of certain electrical features and/or a loss of engine power, power steering assist, and/or power brake booster assist. The loss of any of these features could increase the risk of crash under certain driving conditions.

FOBIK spring back may also cause the disabling of one or more of the vehicle’s safety features including the frontal airbags. This could increase the risk of vehicle occupant injury during a crash.

Chrysler will conduct a voluntary safety recall on all involved vehicles.

Dealers will be notified of the launch of this safety recall by way of established methods used in the past.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries on involved vehicles.

Customer Services Field Operations
Chrysler Group LLC